

**OSLO KOMMUNE**

Geoteknisk konsultants kontor





**SKOVLBORING**

Sted: Yolla

Hull : 6/7 Bilag : 8

Nivå : 96.2 Oppdr: R-252-58

Vannst : \_\_\_\_\_ Dato : 10-2-59

Dybde	Prøve	Sign.	Jordart	Dybde
5			<p>Törrskorpeleire, oksyderte flekker, middels fast leire, siltig, -----, -----, -----, -----, enkelte harde klumper, -----, -----, -----, -----, blöt, -----, -----, -----, -----, -----, -----, -----, -----</p>	5
10				10