

OSLO KOMMUNE, GEOTEKNISK KONSULENT

BORPROFIL

Sted: *Djupdalslinjen 1/ Breivoll*Hull : *18*Nivå : *89.0*Prø : *Skovl*

Aksialdeformasjon %

Bilag : *302*Oppdrag : *R-546a*Dato : *April 70*