

NV: D 3 II

213 N

bygning

Hjørth & Østlyngen 1/6 ← → 1/3 Apothekernes

1. etasje

1. etasje

Prøveserie VI h. 715 m.

Skjærfasthet (s) 1/m²

26	Dyp	W	n	H ₁	ε	D	σ	0	2	4	5 1/m ²
14	1.5	33.4	45			3.0	1.80				
	2.5	58.1	61	27		3.4	1.67				
	3.5	58.8	61	21		3.0	1.65				
	4.5	46.5	56	12		2.3	1.77				
	5.5	44.8	55	14		1.5	1.78				
	6.5	47.2	57	11		1.5	1.77				
	7.5	40.5	53	15	7	1.3	1.84				
	8.5	38.4	52	15	13	1.1	1.87				
	9.5	37.8	52	17	8	1.1	1.87				
100	10.5	39.6	53	20	5	1.0	1.93				
	11.5	41.2	54	15	8	1.0	1.85				
	12.5	40.0	53	33	4	0.9	1.85				
	13.5	40.0	54	20	6	spor	1.86				
	14.5	45.0	56	19	6	spor	1.82				
120	15.5	33.1	48	26	5	spor	1.95				
	16.5	36.2	51	23	5	spor	1.90				
	17.5	36.1	51	37	4.5	spor	1.90				
	18.5	33.6	48	28	6	spor	1.91				
	19.5	31.1	51	28	5	0.9	1.88				
	20.5	34.2	49	20	8	0.9	1.90				

Merknad.
Mosand. fin. gruskorn uren
Mjete. maig
" " "
" " "
" " leirholdig
" " "
Leire mjelig maig
" " "
" " "
" " gruskorn
" " "
" " skjellrest
" " mjeteportier
" " maig
" " "
" " sand-gruskorn
" " "
" " maig



uforskyrret område

NO felg 4186-2
(1959)