

251U SOC1

VISO KOMMUNE
 GEOTEKNISK KONSULENTS KONTOR
 KORROSIJONSSONDERING
 Sted: *Bispelva*

Hull: *4* Bilag: *21*
 Nivå: *1355 m* Oppdr: *12-359*
 Gr.v.st.: _____ Dato: *12-11-63*

| | | | | | | | | | | | |
|-------|------------------|----|----|----|----|----|----|--|--|--|----------------|
| Dybde | Mg/Fe / jord | | | | | | | R ρ pf i ohm. cm | | | K $\cdot 10^3$ |
| | Depolarisasjon % | | | | | | | 100 1000 10000 | | | mm/år |
| | 10 | 20 | 30 | 40 | 50 | 60 | 70 | | | | |

