


1736
5002 I

OSLO HAVNEBASSENG-FORURENSNING	Rapport nr. 924006-3	Figur nr. 06
	Tegner JvdL	Dato
Vingeboring M = 1 : 100	Kontrollert	
Borhull nr. : 106	Godkjent	
Instr. nr. : 20 Vinge : 65 x 130 Dato boret :05.03.92		