


Grundboringer i nr. 2 Kirkegaten.

M. 1:250

K I R K E G A T E N



Jordlagenes bestaffenhed:	Borhul nr.								
	1	2	3	4	5	6	7	8	9
Fyld i meter	2,0	2,0	2,0	2,0	2,0	2,0	1,9	2,0	2,0
Fast sandbl. grå lere "	2,5	1,8	5,0	2,0	2,5	2,85	—	1,4	3,0
Bløt lere "	—	—	—	2,7	0,5	—	—	—	0,75
Sandlag paa fjeld "	—	—	0,1	0,2	0,15	—	—	—	—

SOR 1 II

Brunt betegner terrænghöhe i forhold til ±0
 Blaat — — — fjeldhöhe " — — — " ±0
 Sorte tal over streken angir dybde til fjeld.

Kristiania, Febr. 1918.

Oscarberg
f. Gym

Jordlagenes beskaffenhed:	Borhul nr.								
	1	2	3	4	5	6	7	8	9
Fyld i meter	2,0	2,0	2,0	2,0	2,0	2,0	1,9	2,0	3,0
Fast sandbl. grå lere " "	2,5	1,8	5,0	2,0	2,5	2,85	—	1,4	3,0
Blot lere " "	—	—	—	2,7	0,5	—	—	—	0,75
Sondlag paa fjeld " "	—	—	0,1	0,2	0,15	—	—	—	—