



2376-

OSLO HAVNEBASSENG-FORURENSNING

Rapport nr.
924006-3Figur nr.
05Vingeboring
M = 1 : 100Tegner
JvdLDato
21.04.92

Borhull nr. :105

Instr. nr. : 20
Vinge : 65 x 130
Dato boret :04.03.92Kontrollert
05
Godkjent