


1746
SOQ I

OSLO HAVNEBASSENG-FORURENSNING	Rapport nr. 924006-3	Figur nr. 07
	Tegner JvdL	Dato
Vingeboring M = 1 : 100	Kontrollert	
Borhull nr. : 107	Godkjent	
Instr. nr. : 20 Vingeb : 65 x 130 Dato boret : 05.03.92		