

Fröövrie X i Drammensviken bak Hotel Rose

(Bomingshinn)

(19.2.6)

NV: B1 I

Dybde i m.	glöb nr.	Vekt i gr.			vekt % vund ut totalvund
		Vät lev.	förstap	vund	
5.95	2	6.668	4.600	2.068	31.0
6.10	37	8.355	5.944	2.411	28.8
6.30	8	7.551	5.479	2.072	27.4
6.48	20	7.868	5.849	2.019	25.6
7.05	60	6.326	4.666	1.660	26.2
7.20	114	8.008	5.995	2.013	25.1
7.40	32	5.554	4.038	1.516	27.3
7.60	55	7.644	5.461	2.183	28.5
8.05	57	8.048	6.125	1.923	23.9
8.20	62	9.950	7.269	2.681	27.0
8.40	66	8.854	6.429	2.425	24.4
8.60	107	7.215	5.185	2.030	28.1
9.80	68	5.401	3.744	1.657	30.7
9.95	26	5.593	3.908	1.685	30.2
10.15	108	6.693	4.598	2.095	31.3
10.36	54	6.705	5.040	1.665	24.9

1050