

OSLO KOMMUNE, GEOTEKNISK KONTOR

BORPROFIL / VINGEBOR

Sted: **Ledn. anl. Pilestredet**

Hull : 6

Nivå : 39.5

Pr.φ : 65x130

Aksialdeformasjon %




Bilag : 3

Oppdrag : R-1136

Dato : Sept. 72

Dybde m	Jordart	Symbol	Pr. nr.	Vanninnhold w				Romvekt $\gamma/m^3$	Vingeboring					Sensitivitet
				Plastisk område					2	4	6	8	10	
				20	30	40	50%							
1	Tørrskorpe		1											
2			2											
3			3											
4			4											
5			5											
6	Leire		6											4
7			7											4
8			8											7
9			9											6
10	Kvikk leire		10											8
11			11											8
12	Ant. fjell		12											8
13			13											8
14			14											8
15			15											8
16			16											8
17			17											8
18			18											8
19			19											8
20			20											8
21			21											8
22			22											8
23			23											8
24			24											8
25	25											8		



4  
4  
7  
6  
8  
8  
8