

OSLO KOMMUNE GEOTEKNISK KONTOR  
SKOVLPRÖVE

Sted: Holmlia SO: F15<sup>IV</sup>

Hull: \_\_\_\_\_ Bilag: 47

Nivå: \_\_\_\_\_ Oppdr: R-926

Dato: Sept 77

Merknad	Dybde	Vanninnhold %										Von Post		
		100	200	300	400	500	600	700	800	900				
Hull 506	Nivå 76.0													
Torv	1,35													H5 H6

426 U

Merknad	Dybde	Vanninnhold %										Von Post		
		100	200	300	400	500	600	700	800	900				
Hull 507	Nivå 76.1													
Torv se bilag 54	3.8													H2 H2 H3

427 U

Merknad	Dybde	Vanninnhold %										Von Post		
		100	200	300	400	500	600	700	800	900				
Hull 508	Nivå 76.0													
Torv	6.2													H2 H3 H4 H5 H6 H6

428 U

Merknad	Dybde	Vanninnhold %										Von Post		
		100	200	300	400	500	600	700	800	900				
Hull 509	Nivå 75.9													
Torv	5.9													H2 H2 H2-3 H3 H5 H6

429 U