

104 N

NOD2

● Serie II

34.45 / 14.20
20.25

104 N

Dyb	V	H ₃	H ₁	F	O	K	pH	Anm.
1							7.0	Torrskorpe, rustflekker
2	44.1	605	200	49	0.8	7.9	7.5	Leire
3	56.4	281	42	48	0.8	5.4	7.8	.
4	54.5	104	12	47	0.6	5.1	8.0	.
5	51.1	107	10	38		2.7	8.0	.
6	50.0	58	6.0	34	0.6	1.5	8/9.0	.
7	51.7	60	6.0	36		1.5	8/9.0	.
8	53.0	61	7.0	38	spor	1.6	8/9.0	.
9	49.6	71	6.0	37		1.8	8.5	.
10	51.8	73	6.0	25		1.9	8/9.0	.
11	50.6	88	6.0	34		1.3	8/9.0	.
12	52.4	107	6.0	37		2.7	8/9.0	.
13	51.9	95	6.0	36		2.4	9.0	.
14	51.7	104	8.0	37		2.6	9.0	.
15	49.4	117	8.0	34		2.9	8/9.0	.

NOENSK TERNISK BYGGEKONTROLL
OSLO

Adress: G.G. Tøien, Kv. VII, blokk B.
(Helgesens gt. 76)

16 2 1940

Grunnundersøkelser

NO:D2I

662.

ostin

NOTEBY 662
1940