

310 N

Serie VII

÷ 36 m.
11.2.1941

Dyp i m.	V	H ₃	H ₁	F	O	K	pH	Anm.
1.0	637	31	5	58	1.9	0.7		Leire
2.0	632	47	7	59	1.9	1.1		— " —
3.0	645	61	16	79	2.2	1.4		— " —
4.0	656	56	6	63	2.2	1.2		— " —
5.0	572	79	12	51	1.2	1.8		— " —
6.0	572	55	12	51	1.1	1.3		— " —
7.0	56.5	75	15	52	1.0	1.8		— " —
8.0	552	104	20	54	0.9	2.4		— " —
9.0	56.3	110	16	51	0.9	2.6		— " —
11.0	55.8	79	15	51		1.9		— " —
13.0	56.3	63	15	51		1.6		— " —
15.0	56.2	64	16	51		1.7		— " —

311 N

Serie VII

÷ 2.5 m.
11.2.1941

Dyp i m.	V	H ₃	H ₁	F	O	K	pH	Anm.
1.0	55.5	56	12	47	1.0	1.3		Leire
2.0	55.2	61	15	48	1.1	1.5		— " —
3.0	55.2	66	13	47	1.0	1.6		— " —
4.0	50.2	83	12	38		2.1		— " —
5.0	46.8	153	7	31	0.9			Leire-sandh.

NORSK TEKNISK BYGGEKONTROLL OSLO	
ANLEGG: <i>Strandpromenaden</i> <i>Skarpsno - Bygdøy allé</i>	
DATUM <i>5/9 1941</i>	Grunnundersøkelser
NO. 800	NV: <i>B.1 III</i> <i>B.1 P.</i>